

NTSB Identification: CHI80FA023

14 CFR Part 135 Nonscheduled operation of VOLUNTEER AVIA
 Aircraft: CESSNA 411, registration: N23RJ

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-1153	80/1/24 TIME - 0241	COLUMBUS,OH	CESSNA 411 N23RJ DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-CARGO	COMMERCIAL, AGE 29, 3300 TOTAL HOURS, 20 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - PORT COLUMBUS						
DEPARTURE POINT		INTENDED DESTINATION				
COLUMBUS,OH		LOUISVILLE,KY				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				TAKEOFF: INITIAL CLIMB		
STALL: SPIN				TAKEOFF: INITIAL CLIMB		
PROBABLE CAUSE(S)						
POWERPLANT - FUEL SYSTEM: PUMPS						
MISCELLANEOUS ACTS,CONDITIONS - SHEARED						
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED						
FACTOR(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 2 ENGINES						
FIRE AFTER IMPACT						
REMARKS- L ENG DRIVEN FUEL PUMP SHEARED,L & R AUX FUEL PUMPS FOUND IN LOW POSITION.						

Full narrative is not available