

# NTSB Identification: LAX80FA045

14 CFR Part 91 General Aviation  
Aircraft: AEROSTAR 601P, registration: N8078J

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2787	80/2/4 TIME - 1034	SAN JOSE,CA	AEROSTAR 601P N8078J DAMAGE-DESTROYED	CR- 1 0 0 PX- 1 0 0 OT- 0 0 0	COMMERCIAL MAPPING/PHOTO	ATP, FLIGHT INSTR., AGE 26, 2400 TOTAL HOURS, 15 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - SAN JOSE MUNI						
DEPARTURE POINT		INTENDED DESTINATION				
SAN JOSE,CA		LOCAL				
TYPE OF ACCIDENT				PHASE OF OPERATION		
STALL: SPIN				IN FLIGHT: OTHER		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED						
FIRE AFTER IMPACT						
REMARKS- DRG RADAR VECTOR TO ILS PLT RPRTD HE WOULD BE TAKING PICTURES AT A SLOW SPEED.						

Full narrative is not available