

NTSB Identification: ANC81FA060

14 CFR Part 135 Nonscheduled operation of ALASKA EXPRESS
Aircraft: BEECH G18S, registration: N146PA

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT	PILOT DATA
				F	S	M/N	PURPOSE	
3-3618	81/6/4	ANVIK,AK	BEECH G18S	CR-	1	0	0	AIRLINE TRANSPORT, AGE
	TIME - 1745		N146PA	PX-	0	0	0	37, 12700 TOTAL HOURS,
			DAMAGE-DESTROYED	OT-	0	0	0	327 IN TYPE, INSTRUMENT
								RATED.
	NAME OF AIRPORT - ANVIK							
	DEPARTURE POINT		INTENDED DESTINATION					
	ANVIK,AK		ANCHORAGE,AK					
	TYPE OF ACCIDENT				PHASE OF OPERATION			
	STALL: MUSH				TAKEOFF: INITIAL CLIMB			
	PROBABLE CAUSE(S)							
	PILOT IN COMMAND - FAILED TO ABORT TAKEOFF							
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING							
	MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.							
	FIRE AFTER IMPACT							
	REMARKS- 188LBS OVR MAX GWT.COMPANY FLT PLAN.							

Full narrative is not available