

NTSB Identification: MIA81DA082

14 CFR Part 135 Nonscheduled operation of PINDERS CHARTE
 Aircraft: BRITTNORMAN BN-2A, registration: N28377

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-1061	81/6/2 TIME - 1519	NR.NASSAU,BAHAMAS	BRITTNORMAN BN-2A N28377 DAMAGE-DESTROYED	CR- 0 0 1 PX- 0 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-PASSG	AIRLINE TRANSPORT, AGE 43, 7429 TOTAL HOURS, 2420 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION				
ELEUTHERA,BAHAMAS		NASSAU,BAHAMAS				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE		
DITCHING				LANDING: LEVEL OFF/TOUCHDOWN		
PROBABLE CAUSE(S)						
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
PILOT IN COMMAND - MISMANAGEMENT OF FUEL						
MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION						
FACTOR(S)						
POWERPLANT - POWERPLANT-INSTRUMENTS: FUEL QUANTITY GAUGE						
MISCELLANEOUS ACTS,CONDITIONS - ERRATIC						
MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES						
MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES						
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER						
REMARKS- DITCHED IN INTERNATIONAL WATERS.						

Full narrative is not available