NTSB Identification: MIA81FA072

14 CFR Part 91 General Aviation Aircraft: MITSUBISHI MU-2, registration: N92JR

FILE	DATE LO	OCATION	AIRCRAFT DATA	IN				FLIGHT PURPOSE	PILOT DATA
3-2174	81/5/13 NR.MIAM TIME - 1316 DEPARTURE POINT	,	N92JR DAMAGE-DESTROYED INTENDED DESTINATION	PX-	0	0	1	MISCELLANEOUS TEST	COMMERCIAL, AGE 22, 3260 TOTAL HOURS, 85 IN TYPE, INSTRUMENT RATED.
	MIAMI,FL LOCAL TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION WHEELS-UP PROBABLE CAUSE(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION PILOT IN COMMAND - MISMANAGEMENT OF FUEL MISCELLANEOUS ACTS,CONDITIONS - MISCALCULATED FUEL C MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION FACTOR(S) PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQ COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT- EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON						DNSUMPTION JATE MAINTENANCE AND INSPECTION 2 ENGINES		

Full narrative is not available