NTSB Identification: CHI81FA094

14 CFR Part 91 General Aviation Aircraft: CESSNA 421C, registration: N6867R

	DATE LOCA	TION	AIRCRAFT DATA				FLIGH PURPO		PILOT DATA
879	TIME - 1448		N6867R DAMAGE-DESTROYED	PX-	0	0	PLEASURE		PRIVATE, AGE 54, 1500 TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED.
	DEPARTURE POINT								
	HICKORY,NC	•	COLUMBUS,OH		_				
	TYPE OF ACCIDENT		PHASE OF OPERATION						
	AIRFRAME FAILURE: IN FLIGHT PROBABLE CAUSE(S)		IN FLIGHT: DESCENDING						
	PILOT IN COMMAND - SPATIAL DISORIENTATION PILOT IN COMMAND - EXCEEDED DESIGNED STRESS LIMITS OF AIRCRAFT FACTOR(S) AIRFRAME - WINGS: SPARS AIRFRAME - FLIGHT CONTROL SURFACES: HORIZONTAL STABILIZER, ATTACHMENTS MISCELLANEOUS ACTS, CONDITIONS - OVERLOAD FAILURE WEATHER - THUNDERSTORM ACTIVITY								
		•		JKE					
	WEATHER - THUNDE	RSTORM ACTIV	/ITY		BY	PHO!	IE		
	WEATHER - THUNDE WEATHER - OTHER WEATHER BRIEFING - SKY CONDITION	RSTORM ACTIV	/ITY			EILI	IG AT ACCID	ENT SITE	
	WEATHER - THUNDE WEATHER - OTHER WEATHER BRIEFING - SKY CONDITION BROKEN	RSTORM ACTIV	/ITY		C	EILI 20	IG AT ACCID 00		
	WEATHER - THUNDE WEATHER - OTHER WEATHER BRIEFING - SKY CONDITION BROKEN VISIBILITY AT ACCID	RSTORM ACTIV	/ITY		C	EILI 20 RECI	IG AT ACCID 00 PITATION AT	ACCIDENT SITE	
	WEATHER - THUNDE WEATHER - OTHER WEATHER BRIEFING - SKY CONDITION BROKEN	RSTORM ACTIVE BRIEFED BY FENT SITE	/ITY FLIGHT SERVICE PER:		C P	EILII 20 RECII TH	IG AT ACCID 00 PITATION AT		
	WEATHER - THUNDE WEATHER - OTHER WEATHER BRIEFING - SKY CONDITION BROKEN VISIBILITY AT ACCID 4 MILES OR LESS OBSTRUCTIONS TO VIS	RSTORM ACTIVE BRIEFED BY FROM SITE SITE	/ITY FLIGHT SERVICE PER:		C P T	EILI 20 RECI TH EMPE 87	IG AT ACCID 00 PITATION AT UNDERSTORM,	ACCIDENT SITE RAIN SHOWERS	

Full narrative is not available