

NTSB Identification: FTW66F0391

14 CFR Part 91 General Aviation
Aircraft: STINSON V-77, registration: N69565

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
2-0703	65/11/7 TIME - 0925	LAKE DALLAS TEX	STINSON V-77 N69565 DAMAGE-DESTROYED	CR- 0 1 0 PX- 0 1 2 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	PRIVATE, AGE 46, 2000 TOTAL HOURS, 150 IN TYPE, NOT INSTRUMENT RATED.
NAME OF AIRPORT - SQUIRE HASKINS		TYPE OF ACCIDENT		PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION		COLLIDED WITH: TREES		TAKEOFF: INITIAL CLIMB		
PROBABLE CAUSE(S)		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING			TAKEOFF: INITIAL CLIMB	
MISCELLANEOUS ACTS, CONDITIONS -		ANTI-ICING/DEICING EQUIPMENT-IMPROPER OPERATION OF/OR FAILED TO USE				

Full narrative is not available