

# NTSB Identification: MIA76FKG64

14 CFR Part 91 General Aviation  
 Aircraft: STINSON V-77, registration: N9195H

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0867	76/5/17 TIME - 0750	JONESBORO,GA	STINSON V-77 N9195H DAMAGE-DESTROYED	CR- 0 0 1 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	NO CERTIFICATE, AGE 36, 55 TOTAL HOURS, 0 IN TYPE, NOT INSTRUMENT RATED.
NAME OF AIRPORT - SOUTH EXPRESSWAY DEPARTURE POINT INTENDED DESTINATION JONESBORO,GA LOCAL TYPE OF ACCIDENT PHASE OF OPERATION ENGINE FAILURE OR MALFUNCTION LANDING: FINAL APPROACH COLLIDED WITH: WIRES/POLES LANDING: FINAL APPROACH PROBABLE CAUSE(S) PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION POWERPLANT - FUEL SYSTEM: CARBURETOR MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND FIRE AFTER IMPACT REMARKS- CARB FLOAT PIVOT SHAFT SEPN FM FLOAT HOUSING.						

Full narrative is not available