NTSB Identification: Unknown

14 CFR Part 135 Nonscheduled operation of S.CENT.AIRLINE Aircraft: BEECHCRAFT D18S, registration: N2999

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA

F S M/N PURPOSE

COMMERCIAL, FL.INSTR.,

2-0001 64/2/3 GAINESVILLE FLA BEECHCRAFT D18S CR- 1 0 0 COMMERCIAL CO TIME - 0800 N2999 PX- 9 0 0 AIR TAXI-PASSG AGE 47, 16647 TOTAL DAMAGE-DESTROYED OT- 0 0 0 HOURS, 486 IN TYPE,

INSTRUMENT RATED.

NAME OF AIRPORT - GAINESVILLE MUN
PHASE OF OPERATION
PHASE OF OPERATION STALL TAKEOFF: INITIAL CLIMB PROBABLE CAUSE(S)

MISCELLANEOUS ACTS, CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.

PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING

FIRE AFTER IMPACT

Full narrative is not available