

## NTSB Identification: NYC65F0073

---

14 CFR Part 91 General Aviation

Aircraft: BEECHCRAFT C-18S, registration: N5974V

| FILE   | DATE    | LOCATION  | AIRCRAFT DATA<br>F S M/N PURPOSE | INJURIES                                     | FLIGHT   | PILOT DATA             |
|--------|---------|---|----------------------------------|--|--|------------------------|
| 2-0079 | 65/2/28 | NR.SONORA TEX   | BEECHCRAFT C-18S<br>N5974V       | CR- 2 0 0<br>PX- 4 0 0 BUSINESS<br>OT- 0 0 0 | NONCOMMERCIAL<br>AGE 62, 2326 TOTAL HOURS,<br>13 IN TYPE, NOT<br>INSTRUMENT RATED. | COMMERCIAL, FL.INSTR., |
|        |         | TYPE OF ACCIDENT  |                                  | PHASE OF OPERATION                           |  |                        |
|        |         | COLLISION WITH GROUND/WATER: UNCONTROLLED   |                                  | IN FLIGHT: UNCONTROLLED DESCENT              |  |                        |
|        |         | PROBABLE CAUSE(S)   |                                  |  |  |                        |
|        |         | PILOT IN COMMAND - MISMANAGEMENT OF FUEL  |                                  |  |  |                        |
|        |         | MISSING AIRCRAFT - LATER RECOVERED  |                                  |  |  |                        |
|        |         | REMARKS- RECOVERY DATE-03/03/65.DISORIENTATION OVER DARK SPARCELY LIGHTED TERRAIN |                                  |  |  |                        |

Full narrative is not available