

NTSB Identification: OAK66A0035

14 CFR Part 91 General Aviation
 Aircraft: AERO COMOR 680, registration: N6820S

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
2-0201	66/2/25 TIME - 1307	RED BLUFF CALIF	AERO COMOR 680 N6820S DAMAGE-DESTROYED	CR- 1 0 0 PX- 1 0 0 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	COMMERCIAL, AGE 60, 2000 TOTAL HOURS, 56 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - BIDWELL FIELD						
TYPE OF ACCIDENT						
ENGINE FAILURE OR MALFUNCTION						
STALL: SPIN						
PROBABLE CAUSE(S)						
POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS						
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE						
EMERGENCY CIRCUMSTANCES - PRECAUTIONARY LANDING ON AIRPORT						
FIRE AFTER IMPACT						

Full narrative is not available