

NTSB Identification: NYC69F0278

14 CFR Part 91 General Aviation
Aircraft: CESSNA 411, registration: N162A

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-4883	68/12/6	TETERBORO,NJ	CESSNA 411	CR-	0	1	0	NONCOMMERCIAL
	TIME - 1702		N162A	PX-	0	0	0	CORP/EXEC
			DAMAGE-DESTROYED	OT-	0	0	0	COMMERCIAL, FL.INSTR., AGE 37, 4900 TOTAL HOURS, 150 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - TETERBORO								
TYPE OF ACCIDENT				PHASE OF OPERATION				
ENGINE FAILURE OR MALFUNCTION				TAKEOFF: INITIAL CLIMB				
STALL				TAKEOFF: INITIAL CLIMB				
PROBABLE CAUSE(S)								
POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS								
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED								
FACTOR(S)								
MISCELLANEOUS ACTS,CONDITIONS - IMPROPER EMERGENCY PROCEDURES								
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE								
FIRE AFTER IMPACT								
REMARKS- IMPROPER SINGLE ENG PROCEDURE. FIRE DESTROYED N8822H,N5715V,N9575Q,N7167N,N6416W.N8390N SUBST DMG.								

Full narrative is not available