

NTSB Identification: MIA70A0030

14 CFR Part 135 Scheduled operation of AIR INDIES COR
Aircraft: BEECH C-45H, registration: N9957Z

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3564	69/10/11	NR.LOIZA ALDEA,PR	BEECH C-45H	CR-	0	0	1	COMMERCIAL
	TIME - 1210		N9957Z	PX-	1	4	6	COMMUTER AIR CARRIER
			DAMAGE-DESTROYED	OT-	0	0	0	AIR TAXI-PASSG S-D
NAME OF AIRPORT - SAN JUAN INTL								
DEPARTURE POINT			INTENDED DESTINATION					
	SAN JUAN,PR		ST.THOMAS,VI					
TYPE OF ACCIDENT				PHASE OF OPERATION				
	ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE			
	DITCHING				LANDING: LEVEL OFF/TOUCHDOWN			
PROBABLE CAUSE(S)								
	POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS							
FACTOR(S)								
	MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER							
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING							
PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE								
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE								
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON WATER								
REMARKS- L ENG FAILED,THEN R ENG LOST POWER. DITCHED IN HEAVY SEA 900 FT FROM SHORE. NO PRE-T/O EMERG BRIEF								

Full narrative is not available