## NTSB Identification: LAX71FUM29

14 CFR Part 91 General Aviation Aircraft: BEECH C-45H, registration: N4709C

FILE	DATE	DATE LOCATION AIRCRAFT DATA		INJURIES F S M/N				FLIGHT PURPOSE	PILOT DATA
3-0815	NAME OF AJ DEPARTURE LAKESIDE TYPE OF AG STALL:	IRPORT - LAKESIDE DR POINT E,CALIF CCIDENT MUSH	BEECH C-45H N4709C DAMAGE-DESTROYED OPZONE NTENDED DESTINATION LOCAL	CR- PX- OT-	0	1 0 PHAS	9 0		COMMERCIAL, AGE 53, 2075 TOTAL HOURS, 251 IN TYPE, NOT INSTRUMENT RATED.
	PROBABLE CAUSE(S)  PILOT IN COMMAND - PREMATURE LIFT-OFF PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED FIRE AFTER IMPACT REMARKS- LIFT-OFF APRX 900FT FRM TKOF PSN,AT 75MPH AIRSPEED.OPERATED BY PARACHUTING SCHOOL.								

Full narrative is not available