

NTSB Identification: CHI72AC102

14 CFR Part 135 Nonscheduled operation of QUAKER CITY
 Aircraft: BEECH E18S, registration: N42A

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0675	72/6/22 TIME - 0740	CLEVELAND, OHIO	BEECH E18S N42A DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-CARGO	AIRLINE TRANSPORT, AGE 49, 15176 TOTAL HOURS, 1361 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - CLEVELAND-HOPKINS DEPARTURE POINT PHILADELPHIA, PA INTENDED DESTINATION ROCKFORD, ILL LAST ENROUTE STOP CLEVELAND, OHIO TYPE OF ACCIDENT AIRFRAME FAILURE: IN FLIGHT PHASE OF OPERATION IN FLIGHT: CLIMB TO CRUISE COLLISION WITH GROUND/WATER: UNCONTROLLED IN FLIGHT: UNCONTROLLED DESCENT PROBABLE CAUSE(S) PERSONNEL - MAINTENANCE, SERVICING, INSPECTION: INADEQUATE INSPECTION OF AIRCRAFT (MAINTENANCE PERSONNEL) AIRFRAME - WINGS: SPARS MISCELLANEOUS ACTS, CONDITIONS - FATIGUE FRACTURE FIRE AFTER IMPACT REMARKS- L WING FAILED, FOLDED UP. FATIGUE CRACK WAS PRESENT DURG PRIOR INSPECTIONS BUT WAS NOT DETECTED.						

Full narrative is not available