NTSB Identification: OAK74AP031

14 CFR Part 91 General Aviation Aircraft: PIPER PA-31, registration: N6565L

FILE	DATE LOCATION	AIRCRAFT DATA				FLIGHT PURPOSE	PILOT DATA	
-0403	74/1/11 NOVATO,CALIF TIME - 1438	PIPER PA-31 N6565L DAMAGE-DESTROYED	PX- 6) e	0		COMMERCIAL, AGE 49, 5500 TOTAL HOURS, 500 IN TYPE, INSTRUMENT RATED.	
	NAME OF AIRPORT - GNOSS FIELD							
	DEPARTURE POINT INTENDED DESTINATION							
	SAN FRANCISCO, CALIF							
	TYPE OF ACCIDENT	,		РΗΔ	SF C	F OPERATION		
	COLLISION WITH GROUND/WATER: CONTROLLED				IN FLIGHT: DESCENDING			
	PROBABLE CAUSE(S)							
	PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.							
	PILOT IN COMMAND - CONTINUED VER FLIGHT INTO ADVERSE WEATHER CONDITIONS							
	PILOT IN COMMAND - MISJUDGED ALTITUDE							
	FACTOR(S)							
	WEATHER - LOW CEILING							
	WEATHER - RAIN							
	WEATHER - FOG							
	TERRAIN - HIGH OBSTRUCTIONS							
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE							
	WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT							
	MISSING AIRCRAFT - LATE	R RECOVERED						
	SKY CONDITION					AT ACCIDENT SITE		
	OVERCAST/LOWER SCATTE				1200			
	VISIBILITY AT ACCIDENT	SITE				TATION AT ACCIDEN	T SITE	
	2 MILES OR LESS				AIN			
	OBSTRUCTIONS TO VISION	AT ACCIDENT SITE				TURE-F		
	FOG				45			
	WIND DIRECTION-DEGREES					LOCITY-KNOTS		
	80				8			
	TYPE OF WEATHER CONDITI	CONS				FLIGHT PLAN		
	IFR			S	PECI	AL VFR		
	FIRE AFTER IMPACT REMARKS- RCVRD 1/13/74.SPEC VFR CLNC OUT OF HAMILTON AFB CTL ZONE.HAMILTON 1455PST WX.FLEW INTO HILL.							

Full narrative is not available