

NTSB Identification: FTW76FRG54

14 CFR Part 91 General Aviation
Aircraft: BEECH D18S, registration: N5302U

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES	FLIGHT	PILOT DATA
				F S M/N	PURPOSE	
3-1493	76/5/18	MCALLEN,TX	BEECH D18S	CR- 0 1 0	MISCELLANEOUS	COMMERCIAL, AGE 52, 20000
	TIME - 1453		N5302U	PX- 1 3 0	FERRY	TOTAL HOURS, UNK/NR IN
			DAMAGE-DESTROYED	OT- 0 0 0		TYPE, INSTRUMENT RATED.
	NAME OF AIRPORT - MILLER					
	DEPARTURE POINT		INTENDED DESTINATION			
	MCALLEN,TX		LOCAL			
	TYPE OF ACCIDENT			PHASE OF OPERATION		
	GEAR RETRACTED			TAKEOFF: RUN		
	PROBABLE CAUSE(S)					
	AIRFRAME - LANDING GEAR: SWITCHES,LEVERS,CRANKING MECHANISM,ETC.					
	MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY INSTALLED					
	PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: IMPROPER MAINTENANCE (MAINTENANCE PERSONNEL)					
	FIRE AFTER IMPACT					
	REMARKS- TEST HOP DUE PREV GR MALF. GR CTL SWITCH IMPROPERLY WIRED.					

Full narrative is not available