NTSB Identification: FTW75AF057

14 CFR Part 91 General Aviation Aircraft: DASSAULT FALCON, registration: N990L

FILE	DATE	LOCATION	AIRCRAFT DATA				FLIGHT PURPOSE	PILOT DATA
3-0391	75/3/4 TIME - 06		DASSAULT FALCON N990L DAMAGE-SUBSTANTIAL	PX- 0	0	3		AIRLINE TRANSPORT, AGE 44, 13287 TOTAL HOURS, 1423 IN TYPE, INSTRUMENT RATED.
	NAME OF AIRPORT - NAVY DALLAS							
	DEPARTURE		INTENDED DESTINATION					
	GRAND PRAIRIE, TX WASHINGTON, DC			DUACE OF ODERATION				
	TYPE OF ACCIDENT		PHASE OF OPERATION					
	COLLIDED WITH: FENCE, FENCEPOSTS			TAKEOFF: ABORTED				
	PROBABLE CAUSE(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING							
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.							
	PILOT IN COMMAND - DELAYED ACTION IN ABORTING TAKEOFF							
	MISCELLANEOUS ACTS, CONDITIONS - INCORRECT TRIM SETTING							
	FACTOR(S)							
	AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: WET RUNWAY							
	MISCELLANEOUS ACTS,CONDITIONS - CHECKLIST-FAILED TO USE							
	MISCELLANEOUS ACTS,CONDITIONS - RAN OFF END OF RUNWAY							
	MISCELLANEOUS ACTS,CONDITIONS - AIRCRAFT CAME TO REST IN WATER							
	REMARKS- DIDNT CK STAB TRIM.UN ROTATE ACFT.SPOILERS & DRAG CHUTE NOT DEPLOYED.CRASHED IN LAKE.							TN LAKE

Full narrative is not available