NTSB Identification: OAK78FVM18

14 CFR Part 91 General Aviation Aircraft: BRITTNORMAN BN2A21, registration: N97JA

FILE	DATE	 LOCATION	AIRCRAFT	DATA			IES S M		FLIGHT PURPOSE	PILOT DATA
3-0980	78/4/11 S TIME - 2042	JOSE,CA	BRITTNORMA N97JA DAMAGE-SUB		PX-	0	0	0	MISCELLANEOUS FERRY	AIRLINE TRANSPORT, AGE 48, 12000 TOTAL HOURS, 24 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - REID-HILLVIEW
DEPARTURE POINT INTE
LONG BEACH,CA
TYPE OF ACCIDENT INTENDED DESTINATION

SAN JOSE,CA

PHASE OF OPERATION ENGINE FAILURE OR MALFUNCTION IN FLIGHT: NORMAL CRUISE LANDING: FINAL APPROACH

COLLIDED WITH: WIRES/POLES

PROBABLE CAUSE(S)
PILOT IN COMMAND - MISMANAGEMENT OF FUEL MISCELLANEOUS ACTS, CONDITIONS - FUEL STARVATION

FACTOR(S)

MISCELLANEOUS ACTS, CONDITIONS - FAILURE OF TWO OR MORE ENGINES COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND REMARKS- ACFT EQUIPPED WITH FERRY TANKS.

Full narrative is not available