

NTSB Identification: MIA78FA029

14 CFR General Aviation Form
Aircraft: PIPER PA-31, registration: TIAFY

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
E-0021	78/1/6 TIME - 0935	NR.ANNISTON,AL	PIPER PA-31 TIAFY	CR- PX- OT-	1 0 0	0 0 0	NONCOMMERCIAL CORP/EXEC	COMMERCIAL, AGE 61, 3300 TOTAL HOURS, 600 IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT FT LAUDERDALE,FL		DAMAGE-DESTROYED INTENDED DESTINATION ANNISTON,AL					
	TYPE OF ACCIDENT COLLISION WITH GROUND/WATER: CONTROLLED						PHASE OF OPERATION LANDING: MISSED APPROACH	
	PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER IFR OPERATION							
	FACTOR(S) WEATHER - LOW CEILING WEATHER - FOG							
	WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE							
	WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT							
	SKY CONDITION OVERCAST						CEILING AT ACCIDENT SITE 800	
	VISIBILITY AT ACCIDENT SITE 3 MILES OR LESS						PRECIPITATION AT ACCIDENT SITE NONE	
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE FOG						TEMPERATURE-F 51	
	WIND DIRECTION-DEGREES 80						WIND VELOCITY-KNOTS 4	
	TYPE OF WEATHER CONDITIONS IFR						TYPE OF FLIGHT PLAN IFR	
	FIRE AFTER IMPACT							
	REMARKS-	COSTA RICA REGIS-WX ABOVE MINIMA-ACFT COLLID WI MOUNTAIN AT 1650 FEET 7.5 MILES BEYOND ARPT.						

Full narrative is not available