

NTSB Identification: DEN78FA054

14 CFR Part 91 General Aviation
Aircraft: BEECH 65-A90, registration: N278DU

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-4402	78/7/10	AURORA,CO	BEECH 65-A90	CR-	1	0 0	NONCOMMERCIAL	AIRLINE TRANSPORT, AGE
	TIME - 1046		N278DU	PX-	5	0 0	CORP/EXEC	25, 2715 TOTAL HOURS, 810
			DAMAGE-DESTROYED	OT-	0	0 0		IN TYPE, INSTRUMENT
								RATED.
		NAME OF AIRPORT - STAPLETON INTL						
		DEPARTURE POINT		INTENDED DESTINATION				
		DENVER,CO		RICHFIELD,UT				
		TYPE OF ACCIDENT			PHASE OF OPERATION			
		ENGINE FAILURE OR MALFUNCTION			IN FLIGHT: CLIMB TO CRUISE			
		STALL			LANDING: FINAL APPROACH			
		PROBABLE CAUSE(S)						
		POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS						
		FACTOR(S)						
		POWERPLANT - FUEL SYSTEM: PUMPS						
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
		MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.						
		PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE						
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND						
		FIRE AFTER IMPACT						
		REMARKS- L ENG BOOST PUMP INOP,SWITCH OFF.CROSSFEED OFF.APRX 700# OVR MAX GWT.						

Full narrative is not available