NTSB Identification: MKC78FA055

14 CFR Part 91 General Aviation Aircraft: BEECH 60, registration: N777HH

FILE	DATE	LOCATION	AIRCRAFT DATA					FLIGHT PURPOSE	PILOT DATA
3-3731	TIME - 07!	58	DAMAGE-SUBSTANTIAL	PX-	5	0	0	NONCOMMERCIAL BUSINESS	PRIVATE, AGE 51, 3209 TOTAL HOURS, 338 IN TYPE INSTRUMENT RATED.
	DEPARTURE POINT OLIVIA,MN		INTENDED DESTINATION LAFAYETTE, IN						
	TYPE OF ACCIDENT		•	PHASE OF OPERATION					
	AIRFRAME FAILURE: IN FLI		GHT			I	N F	LIGHT: UNCONTROLLED I	DESCENT
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT PILOT IN COMMAND - EXCEEDED DESIGNED STRESS LIMITS OF AIRCRAFT WEATHER - THUNDERSTORM ACTIVITY WEATHER - TURBULENCE, ASSOCIATED W/CLOUDS AND/OR THUNDERSTORMS FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - SEPARATION IN FLIGHT WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT								
	SKY CONDITION OVERCAST			CEILING AT ACCIDENT SITE UNKNOWN/NOT REPORTED					
	5 OR OVI	Y AT ACCIDENT SITE ER(UNLIMITED)				NO	NE	TATION AT ACCIDENT S	ITE
	OBSTRUCTION NONE	ONS TO VISION AT A	ACCIDENT SITE		Т	YPE IF		WEATHER CONDITIONS	
	IFR FIRE AFTI		RAL DISINTEGRATION.						

Full narrative is not available