

NTSB Identification: DEN79FA005

14 CFR Part 135 Nonscheduled operation of DON ZIMMERMAN  
Aircraft: BEECH 65-80, registration: N886G

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3691	78/10/24	NR.TORREON,NM	BEECH 65-80	CR-	1	0 0	COMMERCIAL	COMMERCIAL, AGE 53, 3665
	TIME - 1004		N886G	PX-	3	0 0	AIR TAXI-PASSG	TOTAL HOURS, UNK/NR IN
			DAMAGE-DESTROYED	OT-	0	0 0		TYPE, NOT INSTRUMENT
								RATED.
		DEPARTURE POINT	INTENDED DESTINATION					
		OBERLIN,KS	PHOENIX,AZ					
		TYPE OF ACCIDENT					PHASE OF OPERATION	
		COLLISION WITH GROUND/WATER: UNCONTROLLED					IN FLIGHT: UNCONTROLLED DESCENT	
		PROBABLE CAUSE(S)						
		PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL						
		PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS						
		PILOT IN COMMAND - SPATIAL DISORIENTATION						
		FACTOR(S)						
		WEATHER - LOW CEILING						
		WEATHER - RAIN						
		WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, BY PHONE						
		WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT						
		SKY CONDITION					CEILING AT ACCIDENT SITE	
		OVERCAST					UNKNOWN/NOT REPORTED	
		VISIBILITY AT ACCIDENT SITE					PRECIPITATION AT ACCIDENT SITE	
		UNKNOWN/NOT REPORTED					RAIN	
		OBSTRUCTIONS TO VISION AT ACCIDENT SITE					TYPE OF WEATHER CONDITIONS	
		UNKNOWN/NOT REPORTED					IFR	
		TYPE OF FLIGHT PLAN						
		NONE						
		REMARKS-	AIRCRAFT INVERTED AT IMPACT.NO INST TIME LOGGED SINCE 11/6/76.MTNS & PASSES OBSCURED.					

Full narrative is not available