

NTSB Identification: MKC79FCG38

14 CFR Part 91 General Aviation
 Aircraft: MITSUBISHI MU-2B, registration: N251M

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0388	79/4/9 TIME - 1350	GARDNER,KS	MITSUBISHI MU-2B N251M DAMAGE-SUBSTANTIAL	CR- 0 0 2 PX- 0 0 1 OT- 0 0 0	NONCOMMERCIAL CORP/EXEC	COMMERCIAL, AGE 26, 1657 TOTAL HOURS, 908 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - GARDNER MUNI						
DEPARTURE POINT		INTENDED DESTINATION				
IOLA,KS		KANSAS CITY,MO				
TYPE OF ACCIDENT				PHASE OF OPERATION		
ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE		
COLLISION WITH GROUND/WATER: CONTROLLED				LANDING: LEVEL OFF/TOUCHDOWN		
PROBABLE CAUSE(S)						
PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: OTHER						
MISCELLANEOUS ACTS,CONDITIONS - WATER IN FUEL						
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES						
EMERGENCY CIRCUMSTANCES - FORCED LANDING ON AIRPORT/SEAPLANE BASE/HELIP.T.						
REMARKS- FUEL TRUCK CONTAMINATED WITH WATER.						

Full narrative is not available