NTSB Identification: DEN79FA048

14 CFR Part 91 General Aviation Aircraft: LEAR JET 25B, registration: N40BC

FILE	DATE	LOCATION	AIRCRAFT DATA	 	RIES S M		FLIGHT PURPOSE	PILOT DATA
3-4005	79/7/6 TIME - 110	PUEBLO,CO 02	LEAR JET 25B N40BC DAMAGE-DESTROYED	0	0	0	INSTRUCTIONAL CHECK	ATP,FLIGHT INSTR., AGE 38, 9576 TOTAL HOURS, 5456 IN TYPE, INSTRUMENT

INTENDED DESTINATION

NAME OF AIRPORT - PUEBLO MEMORIAL
DEPARTURE POINT INTEND
DENVER,CO RETU
TYPE OF ACCIDENT
GROUND-WATER LOOP-SWERVE RETURN

COLLISION WITH GROUND/WATER: UNCONTROLLED

PROBABLE CAUSE(S)
PILOT IN COMMAND - CONTROL INTERFERENCE

FACTOR(S)

PERSONNEL - PRODUCTION-DESIGN-PERSONNEL: POOR/INADEQUATE DESIGN
PILOT IN COMMAND - SPONTANEOUS-IMPROPER ACTION
REMARKS- PIC'S BOOT FND JAMMED IN RUDDER PEDALS,L PEDAL BENT.AD ISSUED TO RPLC HEEL SCUFF PLATES AFT ACDNT.

Full narrative is not available

LAST ENROUTE STOP PUEBLO, CO PHASE OF OPERATION

LANDING: GO-AROUND
LANDING: LEVEL OFF/TOUCHDOWN