NTSB Identification: MIA79FA127

14 CFR Part 91 General Aviation Aircraft: BEECH D18S, registration: N516PA

FILE	DATE	LOCATION	AIRCRAFT DATA	 JUR F			FLIGHT PURPOSE	PILOT DATA
3-3196	79/9/23 TIME - 111	MIRAMAR,FL L6	BEECH D18S N516PA DAMAGE-DESTROYED	 1	0	0	MISCELLANEOUS UNKNOWN/NOT REPORTED	AIRLINE TRANSPORT, AGE 36, 10370 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - NORTH PERRY
DEPARTURE POINT INTENDED DESTINATION
MIRAMAR,FL UNKNOWN/NOT REPORTED

TYPE OF ACCIDENT PHASE OF OPERATION COLLISION WITH GROUND/WATER: UNCONTROLLED TAKEOFF: INITIAL CLIMB

PROBABLE CAUSE(S)
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING
MISCELLANEOUS ACTS, CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G. FIRE AFTER IMPACT REMARKS- ESTIMATED 150LBS OVR MAX GROSS WT & APRX 3 IN AFT OF REAR CG LIMIT.

Full narrative is not available