## NTSB Identification: ATL80FA072

14 CFR Part 91 General Aviation Aircraft: PIPER PA-31P, registration: N776SW

FILE	DATE	LOCATION	AIRCRAFT DATA	 	RIES S M		FLIGHT PURPOSE	PILOT DATA
3-3230	80/7/10 TIME - 085	CHARLESTON,SC 8	PIPER PA-31P N776SW DAMAGE-DESTROYED	 0	4	0	NONCOMMERCIAL BUSINESS	AIRLINE TRANSPORT, AGE 61, 12400 TOTAL HOURS, 705 IN TYPE, INSTRUMENT RATED.

NAME OF AIRPORT - CHARLESTON INTL

DEPARTURE POINT INTENDED DESTINATION

CHARLESTON, SC PADUCAH, KY

TYPE OF ACCIDENT PHASE OF OPERATION

ENGINE FAILURE OR MALFUNCTION IN FLIGHT: NORMAL CRUISE COLLIDED WITH: TREES LANDING: FINAL APPROACH

PROBABLE CAUSE(S)

POWERPLANT - MISCELLANEOUS: POWERPLANT FAILURE FOR UNDETERMINED REASONS PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND REMARKS- UN REACH RWY.R ENG NOT FEATHERED.

Full narrative is not available