

NTSB Identification: DCA82AA007

14 CFR Part 135 Scheduled operation of SUN WEST AIRLI  
Aircraft: PIPER PA-31, registration: N41070

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-3684	81/12/31	DURANGO,CO	PIPER PA-31	CR-	1	0 0	COMMERCIAL	ATP,FLIGHT INSTR., AGE
	TIME - 2000		N41070	PX-	3	2 0	COMMUTER AIR CARRIER	33, 4900 TOTAL HOURS,
			DAMAGE-DESTROYED	OT-	0	0 0	AIR TAXI-PASSG S-D	1381 IN TYPE, INSTRUMENT
								RATED.
		NAME OF AIRPORT - DURANGO-LA PLATA						
		DEPARTURE POINT INTENDED DESTINATION						
		ALBUQUERQUE,NM DURANGO,CO						
		TYPE OF ACCIDENT					PHASE OF OPERATION	
		COLLISION WITH GROUND/WATER: CONTROLLED					LANDING: MISSED APPROACH	
		PROBABLE CAUSE(S)						
		MISCELLANEOUS - UNDETERMINED						
		FACTOR(S)						
		WEATHER - LOW CEILING						
		WEATHER - FOG						
		WEATHER - SNOW						
		WEATHER BRIEFING - NO RECORD OF BRIEFING RECEIVED						
		WEATHER FORECAST - FORECAST SUBSTANTIALY CORRECT						
		SKY CONDITION					CEILING AT ACCIDENT SITE	
		OBSCURATION					400	
		VISIBILITY AT ACCIDENT SITE					PRECIPITATION AT ACCIDENT SITE	
		1 MILE OR LESS					SNOW	
		OBSTRUCTIONS TO VISION AT ACCIDENT SITE					RELATIVE BEARING OF WIND	
		FOG					CALM	
		WIND VELOCITY-KNOTS					TYPE OF WEATHER CONDITIONS	
		CALM					IFR	
		TYPE OF FLIGHT PLAN						
		IFR						
		FIRE AFTER IMPACT						
		REMARKS- PLT FAILED TO EXECUTE SUCCESSFULLY A MISSED APPROACH PROCEDURE FOR UNDETERMINED REASONS.						

Full narrative is not available