

NTSB Identification: LAX81FA120

14 CFR Part 91 General Aviation
 Aircraft: CESSNA T207A, registration: N6441H

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-2947	81/8/18 TIME - 1143	TUSAYAN,AZ	CESSNA T207A N6441H DAMAGE-SUBSTANTIAL	CR- 0 1 0 PX- 0 6 0 OT- 0 0 0	MISCELLANEOUS OTHER	COMMERCIAL, AGE 35, 2690 TOTAL HOURS, 814 IN TYPE, INSTRUMENT RATED.
		NAME OF AIRPORT - GRAND CYN NATL PK				
		DEPARTURE POINT	INTENDED DESTINATION			
		TUSAYAN,AZ	LOCAL			
		TYPE OF ACCIDENT			PHASE OF OPERATION	
		ENGINE FAILURE OR MALFUNCTION			LANDING: TRAFFIC PATTERN-CIRCLING	
		COLLISION WITH GROUND/WATER: CONTROLLED			LANDING: LEVEL OFF/TOUCHDOWN	
		PROBABLE CAUSE(S)				
		PILOT IN COMMAND - MISMANAGEMENT OF FUEL				
		MISCELLANEOUS ACTS,CONDITIONS - FUEL STARVATION				
		FACTOR(S)				
		POWERPLANT - FUEL SYSTEM: SELECTOR VALVES				
		MISCELLANEOUS ACTS,CONDITIONS - OBSTRUCTED				
		TERRAIN - ROUGH/UNEVEN				
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE				
		EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND				
		REMARKS- SIGHT SEEING FLT.15-20GAL FUEL IN R TANK,2GAL FUEL IN L TANK.NO FUEL FLOW FM SEL IN R TANK POS.				

Full narrative is not available