

NTSB Identification: ANC81FA091

14 CFR Part 135 Scheduled operation of KODIAK WESTERN ALASKA A/L INC
Aircraft: CESSNA 207A, registration: N9552M

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|---|------------------|----------------------|----------|---|-----|----------------------|--|
| | | | | F | S | M/N | | |
| 3-3573 | 81/8/4 | NR.DILLINGHAM,AK | CESSNA 207A | CR- | 1 | 0 0 | COMMERCIAL | ATP,FLIGHT INSTR., AGE 34, 3704 TOTAL HOURS, 173 IN TYPE, INSTRUMENT RATED. |
| | | | N9552M | PX- | 0 | 0 0 | COMMUTER AIR CARRIER | |
| | TIME - 1145 | | DAMAGE-DESTROYED | OT- | 0 | 0 0 | AIR TAXI-CARGO S-D | |
| | DEPARTURE POINT | | INTENDED DESTINATION | | | | | |
| | DILLINGHAM,AK | | TOGIAK,AK | | | | | |
| | TYPE OF ACCIDENT | | | | | | PHASE OF OPERATION | |
| | STALL: SPIN | | | | | | IN FLIGHT: OTHER | |
| | PROBABLE CAUSE(S) | | | | | | | |
| | PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED | | | | | | | |
| | FIRE AFTER IMPACT | | | | | | | |
| | REMARKS- COMPANY FLT PLN. | | | | | | | |

Full narrative is not available