

NTSB Identification: Unknown

14 CFR Part 91 General Aviation

Aircraft: AERO COMM 560, registration: N2680B

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES	FLIGHT	PILOT DATA
			F S M/N	PURPOSE		
2-0687	64/9/6	NORCROSS GEORGIA	AERO COMM 560	CR- 0 1 0	NONCOMMERCIAL	COMMERCIAL, AGE 47, 9500
			TIME - 1620	N2680B	PX- 2 4 0 BUSINESS	TOTAL HOURS, 150 IN TYPE,
					DAMAGE-DESTROYED	INSTRUMENT RATED.
					OT- 0 0 0	
						TYPE OF ACCIDENT
						PHASE OF OPERATION
						ENGINE FAILURE OR MALFUNCTION
						IN FLIGHT: NORMAL CRUISE
						COLLIDED WITH: WIRES/POLES
						LANDING: FINAL APPROACH
						PROBABLE CAUSE(S)
						MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION
						PILOT IN COMMAND - FAILED TO SEE AND AVOID OBJECTS OR OBSTRUCTIONS
						PERSONNEL - MISCELLANEOUS-PERSONNEL: GROUND CREWMAN
						PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING
						COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES
						EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND
						REMARKS- FUEL TANK FILLER CAP IMPROPERLY INSTALLED DURING REFUELING

Full narrative is not available