NTSB Identification: Unknown

14 CFR Part 91 General Aviation

Aircraft: BEECHCRAFT D-18S, registration: N80492

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT

F S M/N PURPOSE

3-1498 64/5/31 MEMPHIS TENN BEECHCRAFT D-18S CR- 0 0 1 NONCOMMERCIAL COMMERCIAL, AGE 43, 7708

PX- 0 0 1 CORP/EXEC TIME - 1150 N80492 TOTAL HOURS, 1457 IN

DAMAGE-DESTROYED OT- 0 0 0 TYPE, NOT INSTRUMENT

RATED.

NAME OF AIRPORT - METROPOLITAN TYPE OF ACCIDENT PHASE OF OPERATION

ENGINE FAILURE OR MALFUNCTION TAKEOFF: INITIAL CLIMB COLLIDED WITH: FENCE, FENCEPOSTS TAKEOFF: ABORTED

PROBABLE CAUSE(S)

MISCELLANEOUS ACTS, CONDITIONS - ANTI-ICING/DEICING EQUIPMENT-IMPROPER OPERATION OF/OR FAILED TO USE

WEATHER - RAIN WEATHER - FOG

WEATHER - CONDITIONS CONDUCIVE TO CARB./INDUCTION SYSTEM ICING

WEATHER BRIEFING - BRIEFING RECEIVED-METHOD UNKNOWN WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT

EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND

CEILING AT ACCIDENT SITE SKY CONDITION OVERCAST 2100

VISIBILITY AT ACCIDENT SITE PRECIPITATION AT ACCIDENT SITE

2 MILES OR LESS RAIN

OBSTRUCTIONS TO VISION AT ACCIDENT SITE TYPE OF WEATHER CONDITIONS

FOG BELOW MINIMUMS

TYPE OF FLIGHT PLAN

REMARKS- NON-INSTRUMENT PILOT ATTEMPTED OPERATION IN BELOW VFR MINIMUM CONDITIONS.

Full narrative is not available