

## NTSB Identification: MKC65A0052

14 CFR Part 91 General Aviation

Aircraft: BEECHCRAFT C-45H, registration: N9980Z

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
2-0483	65/3/5	KANSAS CITY KANS	BEECHCRAFT C-45H	CR-	2	0	NONCOMMERCIAL	PRIVATE, AGE 42, 1307
	TIME - 0943		N9980Z	PX-	3	0	BUSINESS	TOTAL HOURS, 83 IN TYPE,
			DAMAGE-DESTROYED	OT-	0	0		INSTRUMENT RATED.
		NAME OF AIRPORT - KANSAS CITY MO.MU						
		TYPE OF ACCIDENT			PHASE OF OPERATION			
		COLLISION WITH GROUND/WATER: UNCONTROLLED			IN FLIGHT: UNCONTROLLED DESCENT			
		PROBABLE CAUSE(S)						
		SYSTEMS - OTHER SYSTEMS: VACUUM SYSTEM						
		INSTRUMENTS/EQUIPMENT AND ACCESSORIES - FLIGHT AND NAVIGATION INSTRUMENTS: ATTITUDE GYRO						
		MISCELLANEOUS ACTS,CONDITIONS - MATERIAL FAILURE						
		REMARKS- A PIECE OF VACUUM HOSE FOUND SPLIT-LEFT VACUUM FLOW VALVE STUCK CLOSED.EVIDENCE GYRO SPEED NOT UP						

Full narrative is not available