NTSB Identification: ANC67A0016

14 CFR Part 135 Nonscheduled operation of NC SIMONSON Aircraft: BEECH C-18S, registration: N445

FILE	DATE	LOCATION	AIRCRAFT DATA		IES S M		FLIGHT PURPOSE	PILOT DATA
2-1183	66/8/15 TIME - 184	ANCHORAGE, ALAS	BEECH C-18S N445 DAMAGE-DESTROYED	 3	0	0	COMMERCIAL AIR TAXI-PASSG	ATP,FLIGHT INSTR., AGE UNK/NR, 3519 TOTAL HOURS, 617 IN TYPE, INSTRUMENT RATED.

TYPE OF ACCIDENT
AIRFRAME FAILURE: IN FLIGHT
COLLISION WITH GROUND/WATER: UNCONTROLLED
PROBABLE CAUSE(S)

AIRFRAME - WINGS: OTHER

MISCELLANEOUS ACTS, CONDITIONS - FATIGUE FRACTURE

FACTOR(S)
MISCELLANEOUS ACTS, CONDITIONS - SEPARATION IN FLIGHT
REMARKS- FATIGUE FRACTURES OCCURED ADJACENT TO LNDG GR SLIDE CLUSTER-RT WING. ACFT WAS PROPERLY MAINTAINED.

Full narrative is not available

PHASE OF OPERATION
IN FLIGHT: NORMAL CRUISE
IN FLIGHT: UNCONTROLLED DESCENT