

NTSB Identification: OAK67A0017

14 CFR Part 135 Nonscheduled operation of CARDINAL AIRWA
Aircraft: BEECH C-18S, registration: N7385C

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-4379	66/8/4	SAN JOSE,CALIF	BEECH C-18S TIME - 0545 N7385C DAMAGE-DESTROYED	CR- 0 0 1 PX- 0 0 8 OT- 0 0 0	COMMERCIAL AIR TAXI-PASSG		COMMERCIAL, AGE 41, 5039 TOTAL HOURS, 167 IN TYPE, INSTRUMENT RATED.	
NAME OF AIRPORT - SAN JOSE MUNI								
TYPE OF ACCIDENT								
ENGINE FAILURE OR MALFUNCTION								
COLLIDED WITH: TREES								
PROBABLE CAUSE(S)								
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING								
MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION								
FACTOR(S)								
MISCELLANEOUS ACTS,CONDITIONS - INATTENTIVE TO FUEL SUPPLY								
MISCELLANEOUS ACTS,CONDITIONS - FAILURE OF TWO OR MORE ENGINES								
COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES								
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND								
REMARKS- AUX TANKS PURPOSELY LEFT EMPTY TO REMAIN BELOW GROSS WEIGHT. NO ENROUTE REFUELING ACCOMPLISHED.								

Full narrative is not available