

NTSB Identification: LAX68A0065

14 CFR Part 135 Scheduled operation of IMPERIAL COMM*
 Aircraft: BEECH E18S, registration: N82B

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4633	68/1/8 TIME - 1040	SAN DIEGO,CALIF	BEECH E18S N82B DAMAGE-DESTROYED	CR- 1 0 0 PX- 2 1 0 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	COMMERCIAL, AGE 40, 7224 TOTAL HOURS, 477 IN TYPE, INSTRUMENT RATED.
		NAME OF AIRPORT - LINDBERGH FIELD				
		TYPE OF ACCIDENT		PHASE OF OPERATION		
		ENGINE FAILURE OR MALFUNCTION		TAKEOFF: INITIAL CLIMB		
		STALL		TAKEOFF: INITIAL CLIMB		
		PROBABLE CAUSE(S)				
		POWERPLANT - COMPRESSOR ASSEMBLY: OTHER				
		MISCELLANEOUS ACTS,CONDITIONS - FATIGUE FRACTURE				
		PILOT IN COMMAND - EXERCISED POOR JUDGMENT				
		PILOT IN COMMAND - IMPROPER IN-FLIGHT DECISIONS OR PLANNING				
		COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE				
		FIRE AFTER IMPACT				
		REMARKS- CRACKED SHROUD,THIRD STAGE STATOR ASSY.PLT USED MIN T/O RUN,MIN T/O SPEED,STEEP CLIMB/TURN AT 50FT				

Full narrative is not available