

NTSB Identification: OAK68F0295

14 CFR Part 135 Nonscheduled operation of HAWAIIAN AIR *
Aircraft: DEHAVILAND DH-104, registration: N4953N

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-0418	68/2/19	HONOLULU,HAWAII	DEHAVILAND DH-104	CR-	0	0	2	AIRLINE TRANSPORT, AGE
	TIME - 1917		N4953N	PX-	0	0	11	37, 4908 TOTAL HOURS, 29
			DAMAGE-SUBSTANTIAL	OT-	0	0	0	IN TYPE, INSTRUMENT
								RATED.
		NAME OF AIRPORT - HONOLULU						
		TYPE OF ACCIDENT					PHASE OF OPERATION	
		HARD LANDING					LANDING: LEVEL OFF/TOUCHDOWN	
		GEAR COLLAPSED					LANDING: LEVEL OFF/TOUCHDOWN	
		PROBABLE CAUSE(S)						
		PILOT IN COMMAND - IMPROPER RECOVERY FROM BOUNCED LANDING						
		FACTOR(S)						
		WEATHER - RAIN						
		MISCELLANEOUS ACTS,CONDITIONS - WINDSHIELD,DIRTY,FOGGY,ETC.-RESTRICTED VISION						
		INSTRUMENTS/EQUIPMENT AND ACCESSORIES - MISCELLANEOUS EQUIPMENT: OTHER						
		MISCELLANEOUS ACTS,CONDITIONS - OVERLOAD FAILURE						
		WEATHER BRIEFING - BRIEFED BY FLIGHT SERVICE PERSONNEL, IN PERSON						
		WEATHER FORECAST - FORECAST SUBSTANTIALLY CORRECT						
		SKY CONDITION					CEILING AT ACCIDENT SITE	
		UNKNOWN/NOT REPORTED					1200	
		VISIBILITY AT ACCIDENT SITE					PRECIPITATION AT ACCIDENT SITE	
		3 MILES OR LESS					RAIN SHOWERS	
		OBSTRUCTIONS TO VISION AT ACCIDENT SITE					TYPE OF WEATHER CONDITIONS	
		NONE					VFR	
		TYPE OF FLIGHT PLAN						
		VFR						
		REMARKS- WINDSHIELD WIPER INOPERATIVE.						

Full narrative is not available