NTSB Identification: ANC69A0034

14 CFR Part 135 Nonscheduled operation of INTERIOR AIR * Aircraft: LOCKHEED L-100, registration: N760AL

ILE	DATE	LOCATION	AIRCRAFT DATA						FLIGHT PURPOSE	PILOT DATA
3-4907	TIME - 0430)	LOCKHEED L-100 N760AL DAMAGE-DESTROYED	PX-	0	0	0		MERCIAL TAXI-CARGO	AIRLINE TRANSPORT, AGE 45, 18000 TOTAL HOURS, 936 IN TYPE, INSTRUMEN RATED.
	NAME OF AIRPORT - BRIT PUT									
	DEPARTURE P		INTENDED DESTINATION							
	FAIRBANKS,ALAS BRIT PUT,ALAS TYPE OF ACCIDENT			г	шлс	E 0	E ODE	DATTON		
	COLLISION WITH GROUND/WATER: CONTROLLED			PHASE OF OPERATION LANDING: GO-AROUND						
	PROBABLE CAUSE(S)									
	PILOT IN COMMAND - CONTINUED VFR FLIGHT INTO ADVERSE WEATHER CONDITIONS									
	PILOT IN COMMAND - DELAYED IN INITIATING GO-AROUND									
	WEATHER - DOWNDRAFT, UPDRAFTS									
	WEATHER - OBSTRUCTIONS TO VISION									
	WEATHER BRIEFING - UNKNOWN/NOT REPORTED									
	WEATHER FORECAST - UNKNOWN/NOT REPORTED									
	SKY CONDITION			CEILING AT ACCIDENT SITE						
	CLEAR							ITED		
	VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE NONE					
	2 MILES OR LESS							DECTT	TON DECREE	
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE				M	50 חאדו		KECII	ION-DEGREES	
	BLOWING SNOW				-		-	LIEAT	THER CONDITIONS	
	WIND VELOCITY-KNOTS 22				- 1	VF		WEAT	HER CONDITIONS	
	TYPE OF FLI	GHT DLAN				VI	IV.			
	IFR	.GITI I LAN								

Full narrative is not available