NTSB Identification: LAX69A0072

14 CFR Part 91 General Aviation Aircraft: AERO COMDR 520, registration: N4127B

FILE	DATE LOCA	ATION AIRCRA					FLIGHT PURPOSE	PILOT DATA	
3-2621		N4127B		(- 0	0	0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	COMMERCIAL, AGE 47, 4100 TOTAL HOURS, 10 IN TYPE, NOT INSTRUMENT RATED.	
	DEPARTURE POINT WILCOX,ARIZ	INTENDED DE PHOENIX,A	STINATION						
	TYPE OF ACCIDENT	ŕ		F	PHAS	ΕО	F OPERATION		
	ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE				
	STALL				IN FLIGHT: OTHER				
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT								
	POWERPLANT - IGNITION SYSTEM: SPARK PLUG								
	MISCELLANEOUS ACTS,CONDITIONS - CARBON DEPOSITS								
	MISCELLANEOUS ACTS, CONDITIONS - EXCESSIVE TEMPERATURE								
	PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED								
	FACTOR(S)								
	WEATHER - HIGH TEMPERATURE								
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE								
	WEATHER BRIEFING - UNKNOWN/NOT REPORTED								
	WEATHER FORECAST -	FORECAST SUBSTANTIAL	LY CORRECT						
	SKY CONDITION			(EIL	ING	AT ACCIDENT SITE		
	CLEAR				UNLIMITED				
	VISIBILITY AT ACCIDENT SITE			F	PRECIPITATION AT ACCIDENT SITE				
	5 OR OVER(UNLIMITED)				NONE TEMPERATURE-F				
	OBSTRUCTIONS TO VISION AT ACCIDENT SITE			7					
	NONE				104				
	WIND DIRECTION-DEGREES			V	WIND VELOCITY-KNOTS				
	110				6				
	TYPE OF WEATHER CONDITIONS			1	TYPE OF FLIGHT PLAN				
	VFR				NONE				
	FIRE AFTER IMPACT								
	REMARKS- PLT KNEW BOTH ENGS WERE UNAIRWORTHY. R ENG FOUND FEATH. L ENG HAD 2 FOULED PLUGS.								

Full narrative is not available