

NTSB Identification: OAK73DJY03

14 CFR Part 135 Nonscheduled operation of LAGOON AVIATIO
 Aircraft: GRUMMAN G44, registration: N4452

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-3964	72/8/1 TIME - 0845	MAJURO, MARSHALL I	GRUMMAN G44 N4452 DAMAGE-DESTROYED	CR- 0 0 1 PX- 0 0 3 OT- 0 0 0	COMMERCIAL AIR TAXI-PASSG	COMMERCIAL, FL. INSTR., AGE 31, 1698 TOTAL HOURS, 21 IN TYPE, INSTRUMENT RATED.
DEPARTURE POINT		INTENDED DESTINATION				
MAJURO, MARSHALL I		ARNO ATOLL LAGOON, MI				
TYPE OF ACCIDENT				PHASE OF OPERATION		
AIRFRAME FAILURE: ON GROUND				LANDING: LEVEL OFF/TOUCHDOWN		
PROBABLE CAUSE(S)						
AIRFRAME - FUSELAGE: OTHER						
MISCELLANEOUS ACTS, CONDITIONS - MATERIAL FAILURE						
FACTOR(S)						
MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER						
REMARKS- HULL BOW SKIN SEPRTD ON WATER LDNG FOR UNDTMD RSN.ACFT SANK, NOT RCVRD.						

Full narrative is not available