

NTSB Identification: CHI71FGD22

14 CFR Part 91 General Aviation

Aircraft: MITSUBISHI MU-2B, registration: N549LK

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N			FLIGHT PURPOSE	PILOT DATA
3-2926	70/10/13 TIME - 1620	NORTHFIELD,OHIO	MITSUBISHI MU-2B N549LK DAMAGE-DESTROYED	CR- PX- OT-	0 0 0	1 0 0	NONCOMMERCIAL CORP/EXEC	COMMERCIAL, AGE 33, 7244 TOTAL HOURS, 995 IN TYPE, INSTRUMENT RATED.
		NAME OF AIRPORT - NORTHFIELD						
		DEPARTURE POINT S	INTENDED DESTINATION CLEVELAND,OHIO					
		TYPE OF ACCIDENT STALL			PHASE OF OPERATION TAKEOFF: INITIAL CLIMB			
		PROBABLE CAUSE(S)						
		PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING						
		PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED						
		FACTOR(S)						
		AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: SOFT RUNWAY						
		MISCELLANEOUS ACTS,CONDITIONS - FAILED TO USE ALL AVAILABLE RUNWAY						
		TERRAIN - HIGH OBSTRUCTIONS						
		REMARKS- ALL RWYS MUDDY.BEGAN T/O ROLL 690 FT SHORT OF DEP END DUE MUD.92 FT TREES ABOUT 60 FT FROM RWY END						

Full narrative is not available