

NTSB Identification: CHI71AC029

14 CFR Part 135 Nonscheduled operation of AMERICAN AVIAT
Aircraft: BEECH D18S, registration: N8999E

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA
				F	S	M/N		
3-2385	70/10/28	PLYMOUTH,MICH	BEECH D18S	CR-	0	1	0	COMMERCIAL
	TIME - 0928		N8999E	PX-	0	2	5	AIR TAXI-PASSG
			DAMAGE-DESTROYED	OT-	0	0	0	COMMERCIAL, FL.INSTR., AGE 36, 4700 TOTAL HOURS, 610 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - PLYMOUTH								
DEPARTURE POINT			INTENDED DESTINATION					
PLYMOUTH,MICH			PELEE,CANADA					
TYPE OF ACCIDENT				PHASE OF OPERATION				
STALL				TAKEOFF: INITIAL CLIMB				
PROBABLE CAUSE(S)								
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING								
MISCELLANEOUS ACTS,CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.								
REMARKS- OBS SAW ACFT PITCH UP SHARPLY. OVER GROSS WT ABOUT 300 LBS,CG ABOUT 5 INCHES AFT LIMITS.								

Full narrative is not available