

NTSB Identification: SEA71FYA32

14 CFR Part 91 General Aviation
Aircraft: CONVAIR 240-14, registration: N1015G

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA		
				F	S	M/N				
3-0075	71/5/14	BUHL, ID	CONVAIR 240-14	CR-	0	0	3	MISCELLANEOUS	COMMERCIAL, AGE 52, 9587	
	TIME - 0702		N1015G	PX-	0	0	0	OTHER PUBLIC	TOTAL HOURS, 2326 IN	
			DAMAGE-SUBSTANTIAL	OT-	0	0	0		TYPE, INSTRUMENT RATED.	
	NAME OF AIRPORT - BUHL MUNICIPAL									
	DEPARTURE POINT		INTENDED DESTINATION							
	TWIN FALLS, ID		LOCAL							
	TYPE OF ACCIDENT			PHASE OF OPERATION						
	ENGINE FAILURE OR MALFUNCTION			IN FLIGHT: CLIMB TO CRUISE						
	WHEELS-UP			LANDING: LEVEL OFF/TOUCHDOWN						
	PROBABLE CAUSE(S)									
POWERPLANT - FUEL SYSTEM: PUMPS										
MISCELLANEOUS ACTS, CONDITIONS - MATERIAL FAILURE										
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.										
MISCELLANEOUS ACTS, CONDITIONS - IMPROPER EMERGENCY PROCEDURES										
MISCELLANEOUS ACTS, CONDITIONS - INTENTIONAL WHEELS-UP										
PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE										
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND										
REMARKS- PROP NOT FEA AS MFG REC. R ENG FUEL FEED VALVE DIAPHRAGM RUPTURED.										

Full narrative is not available