

NTSB Identification: MIA75AM046

14 CFR Part 91 General Aviation
Aircraft: PIPER PA-31, registration: N1FP

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-3246	75/1/19 TIME - 1242	FAIRHOPE,AL	PIPER PA-31	CR-	1	0	0	NONCOMMERCIAL	AIRLINE TRANSPORT, AGE 42, 6800 TOTAL HOURS, 1000 IN TYPE, INSTRUMENT RATED.
			N1FP	PX-	1	0	0	CORP/EXEC	
			DAMAGE-DESTROYED	OT-	0	0	0		
	NAME OF AIRPORT - FAIRHOPE MUNI								
	DEPARTURE POINT		INTENDED DESTINATION						
	HATTIESBURG,MS		FAIRHOPE,AL						
	TYPE OF ACCIDENT				PHASE OF OPERATION				
	COLLISION WITH GROUND/WATER: UNCONTROLLED				LANDING: INITIAL APPROACH				
	PROBABLE CAUSE(S)								
	PERSONNEL - MAINTENANCE,SERVICING,INSPECTION: INADEQUATE MAINTENANCE AND INSPECTION								
	SYSTEMS - FLIGHT CONTROL SYSTEMS: AILERON AND AILERON TAB CONTROL SYSTEM								
	MISCELLANEOUS - FOREIGN MATERIAL AFFECTING NORMAL OPERATIONS								
	MISCELLANEOUS ACTS,CONDITIONS - JAMMED								
	FIRE AFTER IMPACT								
	REMARKS- SCREWDRIIVER INSERTED IN CTL CHAIN BTWN PINS 13-14.FULL R TRAVEL COULD AND DID LOCK AILERON CTL.								

Full narrative is not available