

NTSB Identification: LAX75AL033

14 CFR Part 91 General Aviation
Aircraft: DOUGLAS DC-4B, registration: N39AP

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-0341	75/1/2	NR.DVS-MNTHN AFB,AZ	DOUGLAS DC-4B	CR-	0	0	3	MISCELLANEOUS	COMMERCIAL, AGE 51, 6409 TOTAL HOURS, 20 IN TYPE, INSTRUMENT RATED.
	TIME - 1358		N39AP	PX-	0	0	0	FERRY	
			DAMAGE-DESTROYED	OT-	0	0	0		
	NAME OF AIRPORT - ALLIED AIRSTRIP								
	DEPARTURE POINT		INTENDED DESTINATION		LAST ENROUTE STOP				
	DVS-MNTHN AFB,AZ		DAGGETT,CA		TUCSON,AZ				
	TYPE OF ACCIDENT				PHASE OF OPERATION				
	COLLIDED WITH: WIRES/POLES				TAKEOFF: RUN				
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING								
	PILOT IN COMMAND - LACK OF FAMILIARITY WITH AIRCRAFT								
	PILOT IN COMMAND - FAILED TO ABORT TAKEOFF								
	MISCELLANEOUS ACTS,CONDITIONS - GUST LOCKS ENGAGED								
	FACTOR(S)								
	PERSONNEL - OPERATIONAL SUPERVISORY PERSONNEL: INADEQUATE SUPERVISION OF FLIGHT CREW								
	MISCELLANEOUS - UNQUALIFIED PERSON OPERATED AIRCRAFT								
	AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: OTHER								
	MISCELLANEOUS ACTS,CONDITIONS - CHECKLIST-FAILED TO USE								
	MISCELLANEOUS ACTS,CONDITIONS - DOWNWIND								
	FIRE AFTER IMPACT								
	REMARKS- MECH ACTING AS CO-PLT.3060FT SOFT DIRT STRIP.								

Full narrative is not available