

NTSB Identification: MIA75AM024

14 CFR Part 135 Nonscheduled operation of DORADO WINGS
 Aircraft: BRITTNORM BN-2A, registration: N122DW

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-4013	75/9/15 TIME - 1141	SAN JUAN,PR	BRITTNORM BN-2A N122DW DAMAGE-SUBSTANTIAL	CR- 0 0 1 PX- 0 0 0 OT- 0 0 0	COMMERCIAL AIR TAXI-PASSG	COMMERCIAL, AGE 24, 955 TOTAL HOURS, 105 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - SAN JUAN INTL						
DEPARTURE POINT		INTENDED DESTINATION				
SAN JUAN,PR		DORADO,PR				
TYPE OF ACCIDENT				PHASE OF OPERATION		
COLLIDED WITH: AUTOMOBILE				TAXI: TO TAKEOFF		
PROBABLE CAUSE(S)						
PERSONNEL - MISCELLANEOUS-PERSONNEL: DRIVER OF VEHICLE						
FACTOR(S)						
PILOT IN COMMAND - FAILED TO SEE AND AVOID OBJECTS OR OBSTRUCTIONS						
WEATHER - RAIN						
SKY CONDITION				CEILING AT ACCIDENT SITE		
PARTIAL OBSCURATION				12000		
VISIBILITY AT ACCIDENT SITE				PRECIPITATION AT ACCIDENT SITE		
3/4 MILE OR LESS				RAIN		
OBSTRUCTIONS TO VISION AT ACCIDENT SITE				TEMPERATURE-F		
HAZE				82		
WIND DIRECTION-DEGREES				WIND VELOCITY-KNOTS		
315				8		
TYPE OF WEATHER CONDITIONS				TYPE OF FLIGHT PLAN		
IFR				SPECIAL VFR		
REMARKS- GRND VEHICLE CROSSING ACTIVE TAXIWAY COLLIDED WITH TAXIING ACFT.						

Full narrative is not available