

NTSB Identification: FTW75AF068

14 CFR Part 91 General Aviation
 Aircraft: BEECH D18S, registration: N177V

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-1161	75/5/26 TIME - 2045	NR.LAMESA,TX	BEECH D18S N177V DAMAGE-DESTROYED	CR- 1 0 0 PX- 0 0 0 OT- 0 0 0	NONCOMMERCIAL PLEASURE/PERSONAL TRANSP	COMMERCIAL, AGE 24, 2000 TOTAL HOURS, 150 IN TYPE, INSTRUMENT RATED.
	DEPARTURE POINT ROCKYFORD,CO		INTENDED DESTINATION UNKNOWN/NOT REPORTED		PHASE OF OPERATION IN FLIGHT: NORMAL CRUISE LANDING: ROLL	
	TYPE OF ACCIDENT ENGINE FAILURE OR MALFUNCTION GROUND-WATER LOOP-SWERVE					
	PROBABLE CAUSE(S) POWERPLANT - ENGINE STRUCTURE: MASTER AND CONNECTING RODS MISCELLANEOUS ACTS,CONDITIONS - MATERIAL FAILURE PILOT IN COMMAND - FAILED TO MAINTAIN DIRECTIONAL CONTROL					
	FACTOR(S) TERRAIN - SANDY PARTIAL POWER LOSS - PARTIAL LOSS OF POWER - 1 ENGINE EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND FIRE AFTER IMPACT					
	REMARKS- R ENG FAILED INTERNALLY.					

Full narrative is not available