

NTSB Identification: FTW76FQD17

14 CFR Part 91 General Aviation
 Aircraft: BEECH E18S, registration: N4277B

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-0319	76/3/6	SHAFTER, TX	BEECH E18S	CR-	0	0	1	NONCOMMERCIAL	COMMERCIAL, AGE 34, 5000
	TIME - UNK/NR		N4277B	PX-	0	0	1	BUSINESS	TOTAL HOURS, 3500 IN
			DAMAGE-DESTROYED	OT-	0	0	0		TYPE, INSTRUMENT RATED.
	DEPARTURE POINT		INTENDED DESTINATION						
	UNKNOWN/NOT REPORTED		PONTIAC, MI						
	TYPE OF ACCIDENT								PHASE OF OPERATION
	ENGINE FAILURE OR MALFUNCTION								IN FLIGHT: NORMAL CRUISE
	WHEELS-UP								LANDING: LEVEL OFF/TOUCHDOWN
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - MISMANAGEMENT OF FUEL								
	MISCELLANEOUS ACTS, CONDITIONS - FUEL STARVATION								
	MISCELLANEOUS ACTS, CONDITIONS - INTENTIONAL WHEELS-UP								
	FACTOR(S)								
	POWERPLANT - FUEL SYSTEM: OTHER								
	MISCELLANEOUS ACTS, CONDITIONS - UNAPPROVED MODIFICATION								
	TERRAIN - ROUGH/UNEVEN								
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES								
	EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND								
	FIRE AFTER IMPACT								
	REMARKS- 3-80GAL TANKS INSTALLED IN FUSELAGE.								

Full narrative is not available