NTSB Identification: CHI76AC001

14 CFR Part 91 General Aviation Aircraft: GATES LEAR 25B, registration: N428JX

FILE	DATE LOCAT	ION AIRCRAFT DATA	INJURIES FLIGHT F S M/N PURPOSE	PILOT DATA
3-2095	75/7/3 OSTON,IN TIME - 0756	GATES LEAR 25B N428JX DAMAGE-DESTROYED	CR- 0 0 2 NONCOMMERCIAL PX- 0 0 6 CORP/EXEC OT- 0 0 0	AIRLINE TRANSPORT, AGE 34, 6800 TOTAL HOURS, 1600 IN TYPE, INSTRUMENT RATED.
	NAME OF AIRPORT - RICHMOND MUNI			
	DEPARTURE POINT	INTENDED DESTINATION	LAST ENROUTE STOP	
	TOLEDO,OH	FARMINGDALE, NY	BOSTON, IN	
	TYPE OF ACCIDENT		PHASE OF OPERATION	
	COLLIDED WITH: TR	EES	TAKEOFF: ABORTED	

COLLIDED WITH: TREES

PROBABLE CAUSE(S)

COPILOT - SPONTANEOUS-IMPROPER ACTION

COPILOT - IMPROPER OPERATION OF POWERPLANT & POWERPLANT CONTROLS

PILOT IN COMMAND - INADEQUATE SUPERVISION OF FLIGHT

FACTOR(S)

MISCELLANEOUS ACTS, CONDITIONS - RAN OFF END OF RUNWAY

FIRE AFTER IMPACT REMARKS- BOTH ENGINES AT OR NEAR T.O. PWR AT IMPACT.

Full narrative is not available