

NTSB Identification: MIA77FA049

14 CFR Part 91 General Aviation  
Aircraft: MITSUBISHI MU-2B, registration: N100SW

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES			FLIGHT PURPOSE	PILOT DATA	
				F	S	M/N			
3-1179	77/4/1 TIME - 1620	NR.AUGUSTA,GA	MITSUBISHI MU-2B	CR-	0	2	0	MISCELLANEOUS	COMMERCIAL, AGE 43, 15000 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED.
			N100SW	PX-	0	0	0	FERRY	
			DAMAGE-DESTROYED	OT-	0	0	0		
	DEPARTURE POINT		INTENDED DESTINATION						
	ATLANTA,GA		AUGUSTA,GA						
	TYPE OF ACCIDENT				PHASE OF OPERATION				
	ENGINE FAILURE OR MALFUNCTION				IN FLIGHT: NORMAL CRUISE				
	COLLIDED WITH: TREES				LANDING: FINAL APPROACH				
	PROBABLE CAUSE(S)								
	PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING								
	PILOT IN COMMAND - MISMANAGEMENT OF FUEL								
	MISCELLANEOUS ACTS,CONDITIONS - INATTENTIVE TO FUEL SUPPLY								
	MISCELLANEOUS ACTS,CONDITIONS - FUEL EXHAUSTION								
	FACTOR(S)								
	TERRAIN - ROUGH/UNEVEN								
	COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-2 ENGINES								
	EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND								

Full narrative is not available